

FIG. 1



Shinobu TANAKA Q77969 UNQUALIFIED PERSON DRIVING PREVENTION Filing Date: October 30, 2003 Darryl Mexic 202-663-7909 2 of 4

¥į




POWER SOURCE UNIT

MODULATION UNIT CONTROLLER

BUZZER RELAY

Shinobu TANAKA Q77969 UNQUALIFIED PERSON DRIVING PREVENTION Filing Date: October 30, 2003 Darryl Mexic 202-663-7909 3 of 4


F1 G.3



5

Filing Date: October 30, 2003 Darryl Mexic 202-663-7909

4 of 4



- S1 KEY SWITCH TURNED ON?
- S2 SOUND BUZZER FOR t1 TIME PERIOD
- S3 TAG DETECTED?

4

- S4 TURN ON POWER SOURCE OF FORKLIFT
- S5 TURN OFF POWER SOURCE OF FORKLIFT
- S6 TAG DETECTED?
- S7 TURN ON POWER SOURCE OF FORKLIFT
- S8 t2 TIME PERIOD HAS ELAPSED?
- S9 TAG DETECTED?
- S10 SOUND BUZZER
- S11 t3 TIME PERIOD HAS ELAPSED?
- S12 TURN OFF POWER SOURCE OF FORKLIFT
- S13 STOP BUZZER